


Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Nearest MH	Ground Condition	Notification Made?
D1028-161	Dye	4/22/2009	ADS/TM	S07WW_010MH	Damp	NA
Address 3510 Liberty Heights Avenue			Location Curb	Status Public	Source Catch Basin	



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary


Test ID	Test Type	Date Inspected	Company / Super.	Nearest MH	Ground Condition	Notification Made?
D1028-161	Dye	4/22/2009	ADS/TM	S07WW_010MH	Damp	NA
Address 3510 Liberty Heights Avenue		Location Curb		Status Public	Source Catch Basin	

Observations & Photos

Obs_ID D1028-161-OB01

Nearest MH S07WW_010MH

Comments Dye observed 3.0 ft. downstream of S07WW_010MH. Infiltration gusher at joint at 10 o'clock.



Picture \D1028-161-OB01-P01.jpg

Comments 3.0 ft. downstream of S07WW_010MH along S07WW_010G1.

Obs_ID D1028-161-OB02

Nearest MH S07WW_010MH

Comments Dye observed in wall of S07WW_010MH. Infiltration runner.



Picture \D1028-161-OB02-P01.jpg


Comments At manhole S07WW_010MH.

Smoke and Dye Testing Summary

High Level Sewershed


Run Summary

Run Summary								
Test ID	Test Type	Date Inspected	Company / Super.	Nearest MH	Ground Condition	Notification Made?		
D1028-161	Dye	4/22/2009	ADS/TM	S07WW_010MH	Damp	NA		
Address	3510 Liberty Heights Avenue		Location	Curb	Status	Public	Source	Catch Basin
Obs_ID	D1028-161-OB03			Obs_ID	D1028-161-OB04			
Nearest MH	S07WW_010MH			Nearest MH	S07WW_010MH			
Comments	Dye observed in bench of S07WW_010MH. Infiltration runner.			Comments	Dye observed 14.9 ft. downstream of S07WW_010MH. Infiltration runner at joint at 8 o'clock.			



Picture \D1028-161-OB03-P01.jpg

Comments At manhole S07WW_010MH.



Picture \D1028-161-OB04-P01.jpg

Comments 14.9 ft. downstream of S07WW_010MH along S07WW_010G1.
